



BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone		Ward No.		Ward Name			
YELAHANKA		9		Vidyaranyaapura			
Street ID		Street Name		Significant Landmark			
W0905, W0584, W0895		NA		Puttananjappa layout 5th main I F of Shiva temple			
Segment No.		Total Length (m)					
9/C-W0905/S055437		87.87					
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	87.87	77.565632	13.058955	77.566015	13.058284	W0584	W0895
Work Details							
History of Road / Lane / Circles							
Name of the Work		Sanctioned Estimated Amount (Rs.)			Sanctioned Year		
Improvements to Roads and drain at Puttananjappa layout 5th main I F of Shiva temple in Ward no 09 (Vidyaranyaapura) Sub-Division Ye		1500000			2016		
Year	Type of Work			Other Work Type			
2016 - 2017	Road						
Tender	Work Details			Job No. / Work Code			
Tender	Improvements to Roads and drain at Puttananjappa layout 5th main I F of Shiva temple in Ward no 09 (Vidyaranyaapura) Sub-Division Yelahanka zone			009-16-000020			
Work Order No.	Work Order Date			Period of Extention			
EE/BTP/BBMP/E-PET/59/2016-17	29/06/2016			60 DAYS			
Defect Liability Period From	Defect Liability Period To			Multiple road involved with the same Job No/ Work Code #			
29/06/2016	28/06/2017			Yes			
Contractor Details							
Name of Contractor		Contractor Reg No (BBMP/PWD)			Expenditure Booked \ Released (Rs)		
T.K.SHANKARAPPA					0.00		
Phone No.	E-Mail ID						
9964440879							

Zone: YELAHANKA

Ward No: 9

Ward Name: Vidyaranyaapura

Street ID: W0905,
W0584,
W0895

Field Inspection Details**Number of Trees**

2

Any Other Information**Name**

JANARDHAN

Date of Inspection

06/08/2016

Remarks

completed

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA**Ward No:** 9**Ward Name:** Vidyaranyaपुरa**Street ID:** W0905,
W0584,
W0895

Road Condition



This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	06/08/2016	05/09/2016	COMPLETED
SE	VASU K M	06/08/2016	05/09/2016	COMPLETED
EE	YARAPPA REDDY	06/08/2016	05/09/2016	COMPLETED
AEE	SHIVAKUMAR	06/08/2016	05/09/2016	COMPLETED
AE	JANARDHAN	06/08/2016	05/09/2016	COMPLETED
AE	JANARDHAN	06/08/2016	05/09/2016	COMPLETED

Zone: YELAHANKA

Ward No: 9

Ward Name: Vidyaranyapura

Street ID: W0905,
W0584,
W0895